

Inspection Photos
Location Name: McCallum Unit 83
Location ID: 324644



Photo 1. Overview of location taken facing northwest.



Photo 2. No bradenhead access apparent. Stained soil at wellhead.

