

Inspection Photos  
081-07099  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #1 sign at location



Inspection Photos  
081-07099  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

Photo #2 Wellhead and TA flowlines.



Inspection Photos  
081-07099  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #3 part of the pad, appeared that some equipment was removed.

