

Inspection Photos
081-07098

Inspection Date: 5/5/2022
All Photos taken by Kris Neidel



Photo #1 sign at wellhead



Inspection Photos
081-07098

Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo #2 wellhead and location flowlines



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
081-07098

Inspection Date: 5/5/2022
All Photos taken by Kris Neidel



Photo #3 gravel near cut side of pad. The Form 27 should address the equipment that was in this area and demonstrate soils are compliant with Table 915-1.