



Inspection Photos
081-07095
Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo #1 sign at location.



Inspection Photos
081-07095
Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo #wellhead and on location flowlines.





Inspection Photos
081-07095
Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo #3 flowline risers from removed equipment. The Form 27 should include an investigation in this area.