

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2022

Submitted Date:

05/06/2022

Document Number:

694500415

FIELD INSPECTION FORM

 Loc ID 313155 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10396
 Name of Operator: SWN PRODUCTION COMPANY LLC
 Address: P.O. BOX 12359
 City: SPRING State: TX Zip: 77391-
Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Maneotis, Karen		Karen_Maneotis@swn.com	
Gee, Liz		liz_gee@swn.com	
Snowden, Russ		Russ_Snowden@swn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264522	WELL	TA	08/05/2013	GW	081-07098	WALKER 3-4	EI

General Comment:

On 5/5/2022 COGCC staff, Kris Neidel inspected the Walker 3-4 location. Conditions were; sunny, 50 degrees, the ground was slightly wet from recent precipitation. This inspection was in preparation of approving a Form 27 for location abandonment. The following was observed: wellhead, no other equipment, there were flowlines at wellhead that were TA. See attached photos.

Inspected Facilities

Facility ID: 264522 Type: WELL API Number: 081-07098 Status: TA Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500416	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747119