



Inspection Photos

081-07161

Inspection Date: 5/5/2022

All Photos taken by Kris Neidel

Photo #1 sign at location. Well was PA wellhead was cut off. Wellhead excavation was still open.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

081-07161

Inspection Date: 5/5/2022

All Photos taken by Kris Neidel

Photo #2 On location flowlines near former wellhead. Soil disturbance at area of former wellhead.



Inspection Photos
081-07161

Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo # old wellhead in debris pile.





Inspection Photos
081-07161

Inspection Date: 5/5/2022
All Photos taken by Kris Neidel

Photo #4 sign and soil pile is area of former wellhead.



Inspection Photos

081-07161

Inspection Date: 5/5/2022

All Photos taken by Kris Neidel

Photo #5 looking southwest off pad.