



Inspection Photos  
081-07362  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

Photo #1 Sign



Inspection Photos  
081-07362  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

**Photo #2 wellhead and flowline risers.**





Inspection Photos  
081-07362  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel

Photo #3 looking south at wellhead.



Inspection Photos  
081-07362  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #4 cement truck



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #5 "Continental Services" trailer.

Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #6 BOP



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #7 "Continental Services" rig.



Inspection Photos  
081-07362  
Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



**Photo #8 flowline riser and gathering line riser to the east side of pad.**



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



**Photo #9 pipe on trailer. Not dripping fluid.**



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #10 Rig trailer.



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



**Photo #11 Open top tank. Well head is near front bucket of backhoe.**



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



**Photo #12 water in open top tank.**



Inspection Photos

081-07362

Inspection Date: 5/5/2022

All Photos taken by Kris Neidel



**Photo #13 close up of wellhead and cellar ring.**



Inspection Photos  
081-07362

Inspection Date: 5/5/2022  
All Photos taken by Kris Neidel



Photo #14 Cement truck. "Continental Services"

