

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2022

Submitted Date:

05/06/2022

Document Number:

694500425

FIELD INSPECTION FORMLoc ID 313182 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10396

Name of Operator: SWN PRODUCTION COMPANY LLC

Address: P.O. BOX 12359

City: SPRING State: TX Zip: 77391-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Snowden, Russ		Russ_Snowden@swn.com	
Rowell, Cheryl	713-542-0648	Cheryl_Rowell@swn.com	Senior Reg Analyst
Fischer, Alex		alex.fischer@state.co.us	
Gee, Liz		liz_gee@swn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270386	WELL	TA	10/03/2009	GW	081-07160	WALKER 2-12	EI

General Comment:

On 5/5/2022 COGCC staff, Kris Neidel inspected the Walker 2-12 location. Conditions were; sunny, 50 degrees, the ground was slightly wet from recent precipitation. This inspection was in preparation of approving a Form 27 for location abandonment. The following was observed: wellhead, there were flowlines at wellhead that were TA, See attached photos.

