

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32NENE

Location ID: 323870



Photo #6619 from entrance to location.



Photo #6620 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32NENE

Location ID: 323870



Photo #6622 Loadline open ended.