

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 1 – Location sign**



**Photo 2 – Location photo.**

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 3 – Former battery area.**



**Photo 4 – Open excavation.**

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 5 – Open excavation; fencing down.**



**Photo 6 – Downed fencing.**

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 7 – Downed fencing. Pipes sticking out of sidewall of open excavation.**



**Photo 8 – Uncapped monitoring well.**

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 9 – Pipes sticking out of sidewall of open excavation.**



**Photo 10 – Pipes sticking out of sidewall of open excavation.**

**Inspection Photos**  
**HORST-SCHUTT PW Storage Vessel**  
**Spill ID 476532 (CL)/Remediation Project No 14115**



**Photo 11 – Soils stockpiled on site.**



**Photo 12 – Soils stockpiled on site.**