

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 3 – East Side of Gear Box



Photo 4 – East Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 5 – East Side of Gear Box



Photo 6 – Exhaust – Stained Soil

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 7 – West Side of Gear Box



Photo 8 – West Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 9 – West Side of Gear Box



Photo 10 – West Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 11 – West Side of Gear Box



Photo 12 – ECD and Flare

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 13 – Heater Treater and Gas Meters



Photo 14 – Tank Battery

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 15 – Tank Battery Sign