

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314887

Location Name: Wilson Creek Unit-63N94W /27SWSE

Inspection Document #: 702800178

Rio Blanco County, CO

SWSE Section 27 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /27SWSE

Location ID: 314887



5/6/22
+40.192994,-107.920614
298° NW

Photo 1. Photo taken from the east of the Location shows an overview of the Location.



5/6/22
+40.193309,-107.920865
190° S

Photo 2. Photo taken from the south of the Location shows an overview of the Location.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 702800178