

Inspection Photos

API: 009-06568

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 5/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06568 | Date: 5/6/2022

Inspection Photos



Photo 1. Facing west at the location. There are still areas with no vegetation growth..



Inspection Photos



Photo 2. Facing north at the location. There are still areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06568 | Date: 5/6/2022

Inspection Photos



Photo 3. Facing west toward the surrounding undisturbed CRP grassland.

