

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314277

Location Name: Wilson Creek Unit-63N94W/34NWNW

Inspection Document #: 702800183

Rio Blanco County, CO

NWNW Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wilson Creek Unit-
63N94W/34NWNW
Location ID: 314277



Photo 1. Photo taken from the well area shows the excavated area around the well.



Photo 2. Photo taken from the well area shows the excavated area around the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800183

Inspection Photos
Location Name: Wilson Creek Unit-
63N94W/34NWNW
Location ID: 314277



Photo 3. Photo taken from the south of the Location shows flowlines which will need to be removed.



Photo 4. Photo taken from the north of the Location shows buried electrical lines which will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800183

Inspection Photos
Location Name: Wilson Creek Unit-
63N94W/34NWNW
Location ID: 314277



5/6/22
+40.191952,-107.933114
136° SE

Photo 5. Photos shows power lines being decommissioned at the Location.



5/6/22
+40.191868,-107.933246
11° N

Photo 6. Photos shows power lines being decommissioned at the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800183