

# Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314500

Location Name: Wilson Creek Unit-63N94W /35SWSW

Inspection Document #: 702800185

Rio Blanco County, CO

SWSW Section 35 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /35SW

Location ID: 314500



**Photo 1.** Photo taken from the north of the Location shows an overview of the Location.



**Photo 2.** Photo taken from the center of the Location shows a cement production pad and equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800185

Inspection Photos  
Location Name: Wilson Creek Unit-63N94W /35SW  
Location ID: 314500



**Photo 3.** Photo shows a secondary containment BMP filled with fluid. Wildlife protection BMPs to enable wildlife egress are missing or insufficient.



Inspection Photos

Location Name: Wilson Creek Unit-63N94W /35SWW

Location ID: 314500



**Photo 4.** Photo taken from the west of the Location shows stormwater and sediment control BMPs are missing or insufficient. Erosion present throughout the western perimeter of the Location.



**Photo 5.** Refer to Photo 4 comments.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800185

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /35SW

Location ID: 314500



**Photo 6.** Refer to Photo 4 comments.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800185