



Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Location sign.

May 3, 2022 1:56:
+39.3703N -108.6





May 3, 2022 1:56:
+39.3703N -108.6

Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Tank battery on location.



Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Spill/release area.





Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

**Potentially impacted material with
a detectable hydrocarbon odor
(green area).**





Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Close up of the green area in the previous photo.





May 3, 2022 1:59:
+39.3704N -108.6

Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Partially buried produced water tank on location.





Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Wellhead.

May 3, 2022 2:02:
+39.3703N -108.6



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: COAL GULCH 15-9
Location ID: 334470
Spill/Release ID: 482084
Inspection Date: May 3, 2022

Separator and tank battery.



May 3, 2022 1:56:
+39.3702N -108.6

