

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV-67S95W /5NWNW

Location ID: 334627



Photo #6632 from entrance to location.



Photo #6633 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV-67S95W /5NWNW

Location ID: 334627



**Photo #6634 Location lacks stabilization.**



**Photo #6635 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GV-67S95W /5NWNW

Location ID: 334627



**Photo #6637 Insufficient tracking BMP at entrance to location.**