

Final Reclamation Inspection

May 6, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 331171

Inspection Document #: 697503916

Weld County, CO

NESE Section 13 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BOUGE #1
Location ID: 331171



Photo 1. Photo taken from the well location, facing East. Photo illustrates Operator has removed equipment and gravel from all disturbance areas. Photo illustrates the establishment of desirable plant species but it has not met Rule 1004 standards.

Inspection Photos
Location Name: BOUGE #1
Location ID: 331171



Photo 2. Reference photo taken south of the well location, facing South.

Inspection Photos
Location Name: BOUGE #1
Location ID: 331171



Photo 3. Photo taken from the associated tank battery, facing West. Photo illustrates the tank battery is still in use for other nearby wells.