

Interim Reclamation Inspection

May 6, 2022

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 322747

Inspection Document #: 697503918

Weld County, CO

SWSW Section 18 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MONTGOMERY #1-27
Location ID: 322747



Photo 1. Photo taken from the central location, facing East. Photo illustrates Operator has performed preventative weed maintenance.



Inspection Photos
Location Name: MONTGOMERY #1-27
Location ID: 322747



Photo 2. Photo taken from the central location, facing North.
See comments under Photo 1.



Photo 3. Photo taken from the central location, facing South.
See comments under Photo 1.