

Inspection Photos  
Operator: Simcoe  
API: 067-07071  
Date: 5/9/2022



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing largely with smooth brome.



Photo 3. View the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area comprised of ponderosa pine forest with gambel oak, Oregon grape, balsamroot, and muttongrass.