

Inspection Photos  
Location Name: Phillips 23-11  
Location ID: 329379




Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos  
Location Name: Phillips 23-11  
Location ID: 329379



Photo 3: BBLs faded



Photo 4: BBLs not legible

Inspection Photos  
Location Name: Phillips 23-11  
Location ID: 329379



Photo 5: Wellhead



Photo 6: Wellhead