

Inspection Photos
Location Name: SIEBRING-65N63W /32NWNE
Location #: 306088



Photo #1

Siebring CNE-32 (05-123-23967) Wellsite
Temporarily Abandoned | TA



Photo #2

Siebring Pad /5-63-32-16H Tank Battery
Battery site
Inactive / Shut-down
Equipment documented Fac. ID 430337,
Loc. ID 428637