

# Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314496

Location Name: Wilson Creek Unit-62N94W /2NESE

Inspection Document #: 702800188

Rio Blanco County, CO

NESE Section 2 T2N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-62N94W /2NESE

Location ID: 314496



**Photo 1.** Photo taken from the center of the Location shows an overview of production equipment.



**Photo 2.** Photo taken from the center of the Location shows the wellhead.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 702800188

Inspection Photos

Location Name: Wilson Creek Unit-62N94W /2NESE

Location ID: 314496



**Photo 3.** Photos taken from the western perimeter of the Location shows a straw wattle which is not in proper functioning condition to minimize erosion and transport of sediment offsite.



**Photo 4.** Refer to Photo 3 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800188

Inspection Photos  
Location Name: Wilson Creek Unit-62N94W /2NESE  
Location ID: 314496



**Photo 5.** Photos taken from the western perimeter of the Location shows erosion occurring at the edge of the Location, resulting in transport of sediment offsite and offsite degradation.



**Photo 6.** Photo shows a secondary containment BMP. Wildlife protection BMPs to enable wildlife egress were missing or insufficient.

