

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314505

Location Name: Wilson Creek Unit-63N94W /34NESW

Inspection Document #: 702800190

Rio Blanco County, CO

NESW Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NESW

Location ID: 314505



Photo 1. Photo taken from the south of the Location shows an overview of the Location. Photo also shows power lines on the Location are being decommissioned.



Photo 2. Photo shows a secondary containment BMP filled with fluid. Wildlife protection BMPs to enable wildlife egress are missing or insufficient.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800190

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NESW

Location ID: 314505



Photo 3. Photo taken from the east of the Location shows stormwater and sediment control BMPs are missing or insufficient. Erosion is evident on the eastern perimeter of the Location.



Photo 4. Refer to Photo 3 comments.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800190