

# Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314497

Location Name: Wilson Creek Unit-62N94W/2SWNE

Inspection Document #: 702800192

Rio Blanco County, CO

SWNE Section 2 T2N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



**Photo 1.** Photo taken from the well area shows the excavated area around the well. Photo also shows multiple underground pipes and flowlines which will need to be removed for final reclamation.



**Photo 2.** Photo shows flowlines adjacent to the Location which will need to be removed for final reclamation. Note, GPS coordinates are incorrect due to phone GPS malfunction.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800192

## Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



**Photo 3.** Photo shows piles of excavated material at the edge of the Location. No BMPs were observed to prevent soils potentially contaminated with E&P waste from migrating off the Location. Also note the rill occurring (red arrow) due to inadequate stormwater controls.



**Photo 4.** Photo shows a rill occurring (red arrow) due to inadequate stormwater controls. Photo also shows sediment and gravel from the Location is present offsite.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800192

Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



**Photo 5.** Photo shows a properly functioning straw wattle. In other locations at the northwestern edge of the Location erosion was occurring resulting in soil movement offsite.



**Photo 6.** Photo shows a straw wattle not properly maintained. Some erosion was occurring at the edge of the Location resulting in soil movement offsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800192