

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314509

Location Name: Wilson Creek Morrison Unit-63N94W/34SWNE

Inspection Document #: 702800194

Rio Blanco County, CO

SWNE Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Morrison Unit-63N94W
/34SWNE

Location ID: 314509



Photo 1. Photo taken from the south of the Location shows an overview of the Location. Note, GPS coordinates are incorrect due to phone GPS malfunction.



Photo 2. Photo taken from the north of the Location shows equipment at the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800194

Inspection Photos

Location Name: Wilson Creek Morrison Unit-63N94W
/34SWNE

Location ID: 314509



Photo 3. Photo taken at the east of the Location shows rill erosion (red arrow).



Photo 4. Refer to Photo 3 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800194

Inspection Photos
Location Name: Wilson Creek Morrison Unit-63N94W
/34SWNE
Location ID: 314509



Photo 5. Photo taken at the east of the Location shows a straw wattle is no longer in proper functioning condition. Sediment was observed to have moved over the wattle.



Photo 6. Photo taken at the east of the Location shows a straw wattle is no longer in proper functioning condition. Sediment was observed to have moved over the wattle. Note also the unmarked anchor (red arrow).

