


Inspection Photos
Location Name:State of Colorado P#1
Location ID:319692



Photo#1 Production Tank & Produced Water Tank



Photo#2 Produced Water Tank needs filled in underneath

Inspection Photos
Location Name:State of Colorado P#1
Location ID:319692



Photo#3 Graffiti on tank



Photo#4 Broken Glass near production tank

Inspection Photos
Location Name:State of Colorado P#1
Location ID:319692



Photo#5 Separator and ECD



Photo#6 Stained Soil

Inspection Photos
Location Name:State of Colorado P#1
Location ID:319692



Photo#7 Stained Soil



Photo#8 Stained Soil

Inspection Photos
Location Name:State of Colorado P#1
Location ID:319692



Photo#9 Pumpjack & Wellhead

Photo#2