

Inspection Photos

March 15, 2022

Operator: Organic Energy Company LLC- #10759

Location ID: 313364

Location Name: Allen-66N91W /8SESE

Inspection Document #: 702800196

Moffat County, CO

SESE Section 8 T6N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 1. Photo taken from the north of the Location shows an overview of the Location.



Photo 2. Photo taken from the north of the Location shows the sign posted at the Location entrance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800196

Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 3. Photo taken from the south of the Location shows a sign posted at the tank battery.



Photo 4. Photo shows a close-up of the tank battery sign.

Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 5. Photo taken from the center of the Location shows a sign posted at the wellhead.



Photo 6. Photo shows a close-up of the wellhead sign.



Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 7. Photo shows Dalmatian toadflax, a CO State List B Noxious Weed occasionally found in the interim areas.



Photo 8. Photo shows diffuse knapweed, a CO State List B Noxious Weed occasionally found in the interim areas.



Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 9. Photo taken from the west of the Location shows the western interim area dominated by perennial grasses.



Photo 10. Photo taken from the center of the Location shows the interim area which has been reclaimed at the center of the working pad area and is dominated by perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800196

Inspection Photos
Location Name: Allen-66N91W /8SESE
Location ID: 313364



Photo 11. Photo taken from the south of the Location shows a soil stockpile. The stockpile was vegetated with desirable and seeded species but had more annual weeds than the interim areas of the Location. Bull thistle, a CO List B Noxious Weed was present.



Photo 12. Photo taken from the south of the Location shows a soil stockpile vegetated with more annual weeds than the interim areas of the Location.

