

Inspection Photos

API: 055-06214

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/31/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 2. Facing north at west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 3. There is a black pipe sticking out of the fill slope at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 4. Facing east at the location. Perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 5. Facing south at the location. Perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021

Inspection Photos



Photo 6. The pile of rock still remains at the southeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 8/31/2021