

Inspection Photos

API: 055-06221

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/11/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 1. Facing southeast along the access road. There are noxious weeds along the road (Diffuse knapweed). The check dams have filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 2. Facing southeast along the access road toward the location. T-post and sign will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 3. Facing northeast toward the location. Perennial vegetation is established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 4. Facing northwest toward the location. Perennial vegetation is established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 5. There are noxious weeds along the road (Diffuse knapweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022

Inspection Photos



Photo 6. Facing southeast at the south side of the location. The access road continues past the location. This area along the roadside is not stabilized and check dams have filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06221 | Date: 5/11/2022