

Inspection Photos

API: 055-06155

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/11/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022

Inspection Photos



Photo 1. Facing south along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022

Inspection Photos



Photo 2. The road then turns back to the southeast. Areas of the road are stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022

Inspection Photos



Photo 3. Facing northwest further along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022

Inspection Photos



Photo 4. Facing west toward the location. The perennial vegetation has uniformly reestablished at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022

Inspection Photos



Photo 5. Facing northwest toward the location. The perennial vegetation has uniformly reestablished at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 5/11/2022