

# Inspection Photos

STATE 35-09 BIG PIT

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/11/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the Big Pit location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 35-09 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 2.** Center of the Big Pit location. There are noxious weeds (Diffuse knapweed) beginning to grow that will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 35-09 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 3.** West side of the location facing north. Some areas of the location have not establish sufficient vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 35-09 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 4.** Drone aerial photo facing northeast toward the Big Pit location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 35-09 BIG PIT | Date: 5/11/2022