

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



Photo #6638 from entrance to location.



Photo #6639 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



Photo #6640 Loadline open ended.



Photo #6641 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



Photo #6642 Location lacks stabilization.



Photo #6644 Insufficient tracking BMP at entrance to location.