

FORM  
43Rev  
05/21

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

12/02/2021

Document Number:

402885488

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

### Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

### Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith  
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820  
Address: 1875 LAWRENCE ST STE 1150 Fax: ( )  
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

### Identification Information

API Number: 05 - - OGCC Facility ID: 119959 Initial Form 19 or 27 Document number:   
Facility Name: Brookie Facility Number: 31-13 PIT Facility Type: PIT  
Location QtrQtr: NWNE Section: 13 Township: 34S Range: 66W Meridian: 6  
County: LAS ANIMAS Field Name: PURGATOIRE RIVER  
Federal, Indian or State Lease Number:

### Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer  
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

### Rule 909.J Inspection Information

Date the Pit was Inspected 05/06/2021

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

### Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 217823 Facility Name: RITA 41 Facility Type: Oil and Gas Well  
Location: QtrQtr: NWNE Sec: 13 Twp: 34S Range: 66W Meridian: 6  
County Name: LAS ANIMAS Latitude: 37.089150 Longitude: -104.728390

### Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 93317 Document Name: edd2 File Name: 217823 - EDD2 - 8.30.2021.xlsx  
SampleType: Matrix:  
Facility ID: 217823 Sample ID: 630138 Sample Name: Brookie 31-13 Sample Date: 07/22/2021  
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151086-2

Batch ID: 93316	Document Name: edd1	File Name: 217823 - EDD1 - 8.5.2021.xlsx
SampleType:	Matrix:	
Facility ID: 217823	Sample ID: 630137	Sample Name: Brookie 31-13
Collection Point: WellHead	Matrix: WATER	Pre Post: Rule 909.j initial sample
Project Number:	Remediation Number:	Complaint Number:
Inspection Number:	Spill Number:	Laboratory: TestAmerica Inc.
		NOAV Number:
		Lab Sample ID: 280-151086-2

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
217823	402885489	217823 - Report1 - 8.5.2021.pdf	Analytical Laboratory Report	PDF
217823	402885491	217823 - Report2 - 8.30.2021.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/12/2022
Total: 1 comment(s)		