

Inspection Photos
Location Name: Lost Creek 23
Location ID: 305139



Photo 1 – Wellhead – Unused Rods and Stained Soil

Photo 2 – Wellhead – Unused Rods and Stained Soil

Inspection Photos
Location Name: Lost Creek 23
Location ID: 305139



Photo 3 – Unused Tank



Photo 4 – Separator – Unused Parts and Equipment

Inspection Photos
Location Name: Lost Creek 23
Location ID: 305139



Photo 5 – New Tank installed – No Berms

Photo 6 – Separator – Unused Parts and Equipment