

# Inspection Photos

Location Name: Muegge 6-1

Location ID: 319845

May 11, 2022 at 1:35:05 PM  
39.824629,-104.585379  
Adams County  
COGCC



Pic 2 gas meter run, separator, locked shed

May 11, 2022 at 1:36:00 PM  
39.824599,-104.585650  
Adams County  
COGCC



Pic 3 tanks

## Inspection Photos

Location Name: Muegge 6-1

Location ID: 319845

May 11, 2022 at 1:36:48 PM  
39.824564,-104.585759  
Adams County  
COGCC



**Pic 3 tanks hatch**

May 11, 2022 at 1:36:57 PM  
39.824564,-104.585759  
Adams County  
COGCC



**Pic 4 open top tank is approx. 2' from overflowing, precipitation may cause a spill.**

# Inspection Photos

Location Name: Muegge 6-1

Location ID: 319845

May 11, 2022 at 1:38:00 PM  
39.824676,-104.585820  
Adams County  
COGCC



Pic 5 wellhead

May 11, 2022 at 1:38:20 PM  
39.824589,-104.585668  
Adams County  
COGCC



Pic 6 locked shed on location