

Inspection Photos

5/10/2022

Operator: KOCH EXPLORATION COMPANY LLC
- 49100

Location ID: 391071
Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC - 49100

Location ID: 391071



Photo 1: Photos taken from the south end of the Location facing northwest and northeast. Photo provides overview of the Location.

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC - 49100

Location ID: 391071




Photo 2: Photo shows example of vegetation establishment throughout majority of the Location. Green vegetation observed is Halogeton, a Colorado State listed noxious weed.

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC - 49100

Location ID: 391071



Photo 3: Photo taken from the west end of the Location, facing west. Photo shows example of vegetation establishment throughout majority of the Location. Green vegetation observed in photos are predominantly undesirable annual plant species such as Russian thistle (*Salsola* sp.)

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC - 49100

Location ID: 391071



Photo 4: Photos examples showing the single row of straw wattle implemented along perimeter of the Location; erosion logs are the only control measure on site to manage runoff. Photos show BMP has not been installed per good engineering practices (trench and backfilled) or maintained in proper functioning condition.

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC - 49100

Location ID: 391071



Photo 5: See comments under photo 4.