

Inspection Photos

5/10/2022

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312433

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433




Photo 1: Records show well was completed 4/30/1979. Photo left 1960 USGS aerial image showing area of the Location (star) prior to O&G disturbance. Photo right shows location and access road post construction and drilling.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 2: 2019 COGIS aerial image of the Location and access road. Access road did not pre-exist the O&G Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 3: Photos 3-4 taken from the Location. Photos provide an overview of the Location facing north, east, south and west. Shrub establishment evident, however Location remains predominantly bare with undesirable and noxious weeds such as cheatgrass, annual wheatgrass and Halogeton.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 5: Photo left taken from the Location, facing south. Photo shows ~600 stretch of access road that was recontoured/regraded and reclaimed in accordance with 1004 rules. Photo right shows vegetation at reclaimed access road appears to meet 1004 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 6: Photos examples showing remaining access road has not been recontoured/regraded and reclaimed in accordance with 1004 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312433



Photo 7: Photo example showing culvert remaining at access road.

