

# Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314277

Location Name: Wilson Creek Unit-63N94W/34NWNW

Inspection Document #: 702800201

Rio Blanco County, CO

NWNW Section 34 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Wilson Creek Unit-  
63N94W/34NWNW  
Location ID: 314277



**Photo 1.** Photo taken from the well area shows the excavated area around the well.



**Photo 2.** Photo taken from the well area shows the excavated area around the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800201



Inspection Photos  
Location Name: Wilson Creek Unit-  
63N94W/34NWNW  
Location ID: 314277



**Photo 3.** Photo taken from the south of the Location shows flowlines which will need to be removed.



**Photo 4.** Photo taken from the north of the Location shows buried electrical lines which will need to be removed.





Inspection Photos  
Location Name: Wilson Creek Unit-  
63N94W/34NWNW  
Location ID: 314277



**Photo 5.** Photos shows power lines being decommissioned at the Location.



**Photo 6.** Photos shows power lines being decommissioned at the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800201