

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SWSE

Location ID: 334905



Photo #6690 from entrance to location.



Photo #6691 Loadline open ended.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SWSE

Location ID: 334905



**Photo #6692 Insufficient tracking BMP at entrance to location.**



**Photo #6693 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SWSE

Location ID: 334905



**Photo #6694 Location lacks stabilization.**



**Photo #6695 Location lacks stabilization.**