

Inspection Photos
Location Name: Lost Creek 5
Location ID: 331882



Photo 1 – Wellhead



Photo 2 – Wellhead Sign – API # NOT accurate

Inspection Photos
Location Name: Lost Creek 5
Location ID: 331882



Photo 3 – Tank Battery



Photo 4 – Tank Battery



Inspection Photos
Location Name: Lost Creek 5
Location ID: 331882



Photo 5 – Stained Soil at Separator



Photo 6 – Separator

Inspection Photos
Location Name: Lost Creek 5
Location ID: 331882



Photo 7 – Trash, Debris, Unused Parts and Equipment




Photo 8 – Water Tank – Labels and Cover

Inspection Photos
Location Name: Lost Creek 5
Location ID: 331882



Photo 9 – Unused Equipment