

Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#1 Production Tank



Photo#2 Pumpjack

Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#3 No bullplug on loadout line



Photo#4 Separator, Gas Meter and Bit Coin mining operations



Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#5 Bitcoin mining operations



Photo#6 Bitcoin mining operations



Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439




Photo#7 Produced water pit/**Venting out the top Opgal**  
**camera video attatched in inspection document**



Photo#8 Bitcoin mining operations

Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#9 Bitcoin mining operations



Photo#10 Propane tank hooked up to Bitcoin mining operations



Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#11 Connection from sales meter to natural gas generators



Photo#12 Stained Soil



Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#13 **Stained soil**



Photo#14 **Bitcoin mining operations on concrete slab**



Inspection Photos  
Location Name: Hosmer 4-6  
Location ID:320439



Photo#15Natural Gas generator