

Inspection Photos
Location Name: Jacks Draw Unit No. 17
Location ID: 313098



Photo 1. Breach in berm on access road where sediment is migrating off of the road.



Photo 2. Breach in berm on access road where sediment is migrating off of the road.