

Inspection Photos
Location Name: Jacks Draw Unit 3
Location ID: 312824



Photo 1. Chemical containers stored on location without secondary containment.

