

Inspection Photos

5/16/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335594

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335594



Photo 1: Photos taken from the north end of the Location, facing north/ northeast. Photos provide an overview of the un-stabilized slopes. BMPs to minimize erosion, degradation, and to stabilize the slopes have not been installed or maintained in proper functioning condition; erosion degradation to the slopes has persisted.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335594



Photo 2: Photo taken from the disturbed slopes on the north end of the Location. Photo shows BMPs to minimize erosion , degradation and to stabilize the slopes have not been installed or maintained. Arrow shows example areas where additional erosion is apparent.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 3: Photo taken from the disturbed slopes on the north end of the Location. Photo shows BMPs to minimize erosion , degradation and to stabilize the slopes have not been installed or maintained. Arrow shows example areas where additional erosion is apparent.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 4: Photo taken from the disturbed slopes on the north end of the Location. Photo shows BMPs to minimize erosion , degradation and to stabilize the slopes have not been installed or maintained. Arrow shows example areas where additional erosion is apparent.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335594



Photo 5: Operator appears to have removed shrub vegetation from areas on the north end of the Location, including the slopes. Vegetation has been piled on the west end of the Location, is considered debris and requires removal.