

Inspection Photos

5/16/2022

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 458475

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 1: Photos taken from southwest end of the Location, facing west and north. Photos provide overview of the Location. Photos also show interim reclamation of the Location has not been conducted in accordance with 1003 rules; records show all wells on the location have either been plugged, or have been drilled and producing since 11/3/2020; pursuant to Rule 1003.b, interim reclamation required by 5/3/2021.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 2: Fluids observed spilling from connection point of the line and tank (yellow arrow) onto the working pad surface. Stained soils also evident beneath the tank. (red arrow).



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



May 16, 2022
39.69370033N 108.12592676W



May 16, 2022
39.69368279N 108.12590169W

Photo 3: Continued from photo 2. Photo left shows stained soils beneath tank. Photo right show incorrect Operator information and missing capacity labeling.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 4: Photos 4-7 taken throughout the Location. Photos show examples of various trash, debris and unused equipment stored on the Location. Photos also provide examples showing interim reclamation of the Location has not been completed in accordance with 1003 rules.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 6: See comments under photo 4.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 7: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 8: Photo shows tank next to the Location entrance, on the east end of the Location. Photo show containment BMP has not been maintained in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 458475



Photo 9: Photo taken from the topsoil stockpile on the north end of the Location. Photo shows Operator has constructed a pipeline that runs on the east, and north end of the Location; pipeline has been constructed directly upon the topsoil stockpiles along the perimeter of the Location. This does not appear to be protective of soils per with Rule 1002.c. Additionally, soils are exposed and at risk to erosion.