

Colorado Oil and Gas Conservation Commission





UPV #5-5J3 Issue Report

Created on May 17, 2022

Captured on May 16, 2022



Type	Count
Observation	2

No.	Type	Severity	Created	Status	Cost of Repair
1	 Observation	—	May 17, 2022	Open	—
2	 Observation	—	May 17, 2022	Open	—
					Total: \$0.00

2 - Observation

Open

May 16, 2022 at 10:01am



Map data ©2022 Imagery ©2022 , Maxar Technologies

Details

Summary:	Unused Equipment
Created:	May 17, 2022, 3:06pm by Adam Burns
Cost of Repair:	—
Coordinates:	40.25712, -104.46756
Area:	1393.36 ft ²
Surface Area:	2344.36 ft ²

1 - Observation

Open

May 16, 2022 at 10:01am



Details

Summary:	Unused Equipment
Created:	May 17, 2022, 3:06pm by Adam Burns
Cost of Repair:	—
Coordinates:	40.25740, -104.46742
Area:	1238.13 ft ²
Surface Area:	1518.80 ft ²

