

Inspection Photos
Operator: Enduring
API: 067-08647
Date: 5/13/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, Indian ricegrass, rubber rabbitbrush, and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open field with rubber rabbitbrush, western wheatgrass, and crested wheatgrass.