

Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 1. Overview of location taken facing east.



Photo 2. Road damage on access road.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 3. Culvert that appears damaged or overwhelmed.



Photo 4. Culvert with road damage. Hard hat for scale.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 5. Photo of road damage with sediment transport into field visible in the background.



Photo 6. Close up of sediment transported off of access road.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 7. Meter run with no equipment. Knocked over tank to right and behind meter housing. Equipment parts have become debris to the left of the housing.



Photo 8. Peeling tank label. Knocked over battery sign.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 9. Holes in produced water tank.



Photo 10. Close up of holes in produced water tank.

