

Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 1. Overview of location taken facing southwest.



Photo 2. Equipment stored on location.



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 3. Tank knocked over.



Photo 4. Tank label peeling.



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



**Photo 5. Sediment migration across and off access road.
Hard hat for scale.**



Photo 6. Sediment migration onto and across access road.